



Button Head Socket Screw - Metric - Gr 10.9

M3 x 0.5 p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
5mm	U27 03005??	100	100
6mm	U27 03006??	100	100
8mm	U27 03008??	100	100
10mm	U27 03010??	100	100
12mm	U27 03012??	100	100
16mm	U27 03016??	100	100
20mm	U27 03020??	100	100
25mm	U27 03025??	100	100
30mm	U27 03030??	100	100



Wrench size 2.0mm

Replace ?? With PL = Plain or ZP = Zinc

M4 x 0.7 p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
6mm	U27 04006??	100	100
8mm	U27 04008??	100	100
10mm	U27 04010??	100	100
12mm	U27 04012??	100	100
16mm	U27 04016??	100	100
20mm	U27 04020??	100	100
25mm	U27 04025??	100	100
30mm	U27 04030??	100	100
35mm	U27 04035??	100	100
40mm	U27 04040??	100	100
45mm	U27 04045??	100	100
50mm	U27 04050??	100	100

Wrench size 2.5mm

Replace ?? With PL = Plain or ZP = Zinc

M5 x 0.8 p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
6mm	U27 05006??	100	100
8mm	U27 05008??	100	100
10mm	U27 05010??	100	100
12mm	U27 05012??	100	100
16mm	U27 05016??	100	100
20mm	U27 05020??	100	100
25mm	U27 05025??	100	100

Wrench size 3.0mm

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



Button Head Socket Screw - Metric - Gr 10.9

Continued from previous page

M5 x 0.8 p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
30mm	U27 05030??	100	100
35mm	U27 05035??	100	100
40mm	U27 05040??	100	100
45mm	U27 05045??	100	100
50mm	U27 05050??	100	100
55mm	U27 05055??	100	100
60mm	U27 05060??	100	100
65mm	U27 05065??	100	
70mm	U27 05070??	100	
80mm	U27 05080??	100	



Wrench size 3.0mm

Replace ?? With PL = Plain or ZP = Zinc

M6 x 1.0 p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
8mm	U27 06008??	100	100
10mm	U27 06010??	100	100
12mm	U27 06012??	100	100
16mm	U27 06016??	100	100
20mm	U27 06020??	100	100
25mm	U27 06025??	100	100
30mm	U27 06030??	100	100
35mm	U27 06035??	100	100
40mm	U27 06040??	100	100
45mm	U27 06045??	100	100
50mm	U27 06050??	100	100
60mm	U27 06060??	100	100
65mm	U27 06065??	100	100
70mm	U27 06070??	100	100
75mm	U27 06075??	100	100
80mm	U27 06080??	100	100

Wrench size 4.0mm

Replace ?? With PL = Plain or ZP = Zinc

M8 x 1.25 p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
10mm	U27 08010??	100	100
12mm	U27 08012??	100	100

Wrench size 5.0mm

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



Button Head Socket Screw - Metric - Gr 10.9

Continued from previous page

M8 x 1.25 p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
16mm	U27 08016??	100	100
20mm	U27 08020??	100	100
25mm	U27 08025??	100	100
30mm	U27 08030??	100	100
35mm	U27 08035??	100	100
40mm	U27 08040??	100	100
45mm	U27 08045??	100	100
50mm	U27 08050??	100	100
55mm	U27 08055??	100	100
60mm	U27 08060??	100	100
70mm	U27 08070??	100	100
75mm	U27 08075??	100	100
80mm	U27 08080??	100	100
100mm	U27 08100??	100	100
Wrench size 5.0mm		Replace ?? With PL = Plain or ZP = Zinc	



M10 x 1.5 p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
12mm	U27 10012??	100	100
16mm	U27 10016??	100	100
20mm	U27 10020??	100	100
25mm	U27 10025??	100	100
30mm	U27 10030??	100	100
35mm	U27 10035??	100	100
40mm	U27 10040??	100	100
45mm	U27 10045??	100	100
50mm	U27 10050??	100	100
55mm	U27 10055??	100	100
60mm	U27 10060??	100	100
70mm	U27 10070??	100	100
80mm	U27 10080??	50	50
90mm	U27 10090??	50	50
100mm	U27 10100??	50	50
Wrench size 6.0mm		Replace ?? With PL = Plain or ZP = Zinc	



Button Head Socket Screw - Metric - Gr 10.9

M12 x 1.75 p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
16mm	U27 12016??	100	100
20mm	U27 12020??	100	100
25mm	U27 12025??	100	100
30mm	U27 12030??	100	100
35mm	U27 12035??	100	100
40mm	U27 12040??	100	100
45mm	U27 12045??	100	100
50mm	U27 12050??	100	100
60mm	U27 12060??	50	50
70mm	U27 12070??	50	50
80mm	U27 12080??	50	50
90mm	U27 12090??	50	50
100mm	U27 12100??	50	50



Wrench size 8.0mm

Replace ?? With PL = Plain or ZP = Zinc

M16 x 2.0 p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
50mm	U27 16050??	50	50
60mm	U27 16060??	50	50
70mm	U27 16070??	25	25
80mm	U27 16080??	25	25
90mm	U27 16090??	25	25
100mm	U27 16100??	25	25

Wrench size 10.0mm

Replace ?? With PL = Plain or ZP = Zinc