



Flat Head Socket Screw - UNF - Alloy Steel

#10 Unf - 32 tpi

| Length | Code | Plain | Zinc |
|------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 1/4 | U21 05006?? | 100 | 100 |
| 5/16 | U21 05008?? | 100 | 100 |
| 3/8 | U21 05010?? | 100 | 100 |
| 7/16 | U21 05011?? | 100 | |
| 1/2 | U21 05012?? | 100 | 100 |
| 5/8 | U21 05016?? | 100 | 100 |
| 3/4 | U21 05020?? | 100 | 100 |
| 7/8 | U21 05022?? | 100 | |
| 1" | U21 05025?? | 100 | 100 |
| 1-1/4" | U21 05032?? | 100 | 100 |
| 1-1/2" | U21 05038?? | 100 | 100 |
| 1-3/4" | U21 05045?? | 100 | 100 |
| 2" | U21 05050?? | 100 | 100 |
| 2-1/4" | U21 05057?? | 100 | |
| 2-1/2" | U21 05063?? | 100 | |
| 3" | U21 05075?? | 100 | |
| Wrench size 1/8 | | Replace ?? With PL = Plain or ZP = Zinc | |



1/4 Unf - 28 tpi

| Length | Code | Plain | Zinc |
|------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 3/8 | U21 06010?? | 100 | 100 |
| 1/2 | U21 06012?? | 100 | 100 |
| 5/8 | U21 06016?? | 100 | 100 |
| 3/4 | U21 06020?? | 100 | 100 |
| 7/8 | U21 06022?? | 100 | |
| 1" | U21 06025?? | 100 | 100 |
| 1-1/4" | U21 06032?? | 100 | 100 |
| 1-1/2" | U21 06038?? | 100 | 100 |
| 1-3/4" | U21 06045?? | 100 | |
| 2" | U21 06050?? | 100 | 100 |
| 2-1/4" | U21 06057?? | 100 | |
| 2-1/2" | U21 06063?? | 100 | |
| 3" | U21 06075?? | 100 | |
| 3-1/2" | U21 06088?? | 100 | |
| Wrench size 5/32 | | Replace ?? With PL = Plain or ZP = Zinc | |



Flat Head Socket Screw - UNF - Alloy Steel

5/16 Unf - 24 tpi

| Length | Code | Plain | Zinc |
|------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 3/8 | U21 08010?? | 100 | |
| 1/2 | U21 08012?? | 100 | 100 |
| 5/8 | U21 08016?? | 100 | 100 |
| 3/4 | U21 08020?? | 100 | 100 |
| 7/8 | U21 08022?? | 100 | |
| 1" | U21 08025?? | 100 | 100 |
| 1-1/8" | U21 08028?? | 100 | |
| 1-1/4" | U21 08032?? | 100 | 100 |
| 1-1/2" | U21 08038?? | 100 | 100 |
| 1-3/4" | U21 08045?? | 100 | |
| 2" | U21 08050?? | 100 | 100 |
| 2-1/4" | U21 08057?? | 100 | |
| 2-1/2" | U21 08063?? | 100 | 100 |
| 3" | U21 08075?? | 100 | |
| 3-1/2" | U21 08088?? | 100 | |
| 4" | U21 08100?? | 100 | |
| Wrench size 3/16 | | Replace ?? With PL = Plain or ZP = Zinc | |



3/8 Unf - 24 tpi

| Length | Code | Plain | Zinc |
|------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 1/2 | U21 10012?? | 100 | 100 |
| 5/8 | U21 10016?? | 100 | 100 |
| 3/4 | U21 10020?? | 100 | 100 |
| 7/8 | U21 10022?? | 100 | |
| 1" | U21 10025?? | 100 | 100 |
| 1-1/8" | U21 10028?? | 100 | |
| 1-1/4" | U21 10032?? | 100 | 100 |
| 1-1/2" | U21 10038?? | 100 | 100 |
| 1-3/4" | U21 10045?? | 100 | 100 |
| 2" | U21 10050?? | 100 | 100 |
| 2-1/4" | U21 10057?? | 100 | |
| 2-1/2" | U21 10063?? | 50 | 50 |
| 2-3/4" | U21 10069?? | 50 | |
| 3" | U21 10075?? | 50 | 50 |
| 3-1/2" | U21 10088?? | 50 | |
| Wrench size 7/32 | | Replace ?? With PL = Plain or ZP = Zinc | |



Flat Head Socket Screw - UNF - Alloy Steel

7/16 Unf - 20 tpi

| Length | Code | Plain | Zinc |
|-------------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 3/4 | U21 11020?? | 100 | 100 |
| 1" | U21 11025?? | 100 | 100 |
| 1-1/4" | U21 11032?? | 100 | 100 |
| 1-1/2" | U21 11038?? | 100 | 100 |
| 1-3/4" | U21 11045?? | 100 | 100 |
| 2" | U21 11050?? | 50 | 50 |
| 2-1/2" | U21 11063?? | 50 | 50 |
| 3" | U21 11075?? | 50 | 50 |
| Wrench size 1/4 | | Replace ?? With PL = Plain or ZP = Zinc | |



1/2 Unf - 20 tpi

| Length | Code | Plain | Zinc |
|-------------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 3/4 | U21 12020?? | 100 | 100 |
| 1" | U21 12025?? | 100 | 100 |
| 1-1/4" | U21 12032?? | 100 | 100 |
| 1-1/2" | U21 12038?? | 100 | 100 |
| 1-3/4" | U21 12045?? | 50 | 50 |
| 2" | U21 12050?? | 50 | 50 |
| 2-1/4" | U21 12057?? | 50 | |
| 2-1/2" | U21 12063?? | 50 | 50 |
| 3" | U21 12075?? | 50 | 50 |
| 3-1/2" | U21 12088?? | 25 | |
| 4" | U21 12100?? | 25 | 25 |
| Wrench size 5/16 | | Replace ?? With PL = Plain or ZP = Zinc | |

5/8 Unf - 18 tpi

| Length | Code | Plain | Zinc |
|-------------------------------------|-------------|---|------|
| Pack Quantity (if available) | | | |
| 1" | U21 16025?? | 50 | 50 |
| 1-1/4" | U21 16032?? | 50 | 50 |
| 1-1/2" | U21 16038?? | 50 | 50 |
| 1-3/4" | U21 16045?? | 50 | 50 |
| 2" | U21 16050?? | 50 | 50 |
| 2-1/4" | U21 16057?? | 25 | 25 |
| 2-1/2" | U21 16063?? | 25 | 25 |
| 2-3/4" | U21 16069?? | 25 | |
| 3" | U21 16075?? | 25 | 25 |
| 3-1/2" | U21 16088?? | 25 | 25 |
| 4" | U21 16100?? | 10 | 10 |
| Wrench size 3/8 | | Replace ?? With PL = Plain or ZP = Zinc | |



Flat Head Socket Screw - UNF - Alloy Steel

3/4 Unf - 16 tpi

| Length | Code | Plain | Zinc |
|------------------------------|-------------|-------|------|
| Pack Quantity (if available) | | | |
| 1-1/4" | U21 20032?? | 25 | |
| 1-1/2" | U21 20038?? | 25 | |
| 1-3/4" | U21 20045?? | 25 | |
| 2" | U21 20050?? | 25 | |
| 2-1/4" | U21 20057?? | 25 | |
| 2-1/2" | U21 20063?? | 25 | |
| 3" | U21 20075?? | 25 | |
| 3-1/2" | U21 20088?? | 25 | |
| 4" | U21 20100?? | 10 | |



Wrench size 1/2

Replace ?? With PL = Plain or ZP = Zinc