



UNC Socket Head Cap Screw - Alloy Steel

#10 Unc - 24 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 05005??	3/16	100	
U02 05006??	1/4	100	100
U02 05008??	5/16	100	100
U02 05010??	3/8	100	100
U02 05012??	1/2	100	100
U02 05016??	5/8	100	100
U02 05020??	3/4	100	100
U02 05025??	1"	100	100
U02 05032??	1-1/4"	100	100
U02 05038??	1-1/2"	100	100
U02 05045??	1-3/4"	100	100
U02 05050??	2"	100	100
U02 05057??	2-1/4"	100	100
U02 05063??	2-1/2"	100	100
U02 05075??	3"	100	100
U02 05082??	3-1/4"	100	100
U02 05088??	3-1/2"	100	100
U02 05100??	4"	100	100
U02 05112??	4-1/2"	100	
U02 05125??	5"	100	
U02 05150??	6"	100	



Wrench size 5/32

Replace ?? With PL = Plain or ZP = Zinc

1/4 Unc - 20 tpi


Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 06005??	3/16	100	
U02 06006??	1/4	100	100
U02 06008??	5/16	100	
U02 06010??	3/8	100	100
U02 06012??	1/2	100	100
U02 06016??	5/8	100	100
U02 06020??	3/4	100	100
U02 06022??	7/8	100	100
U02 06025??	1"	100	100
U02 06028??	1-1/8"	100	
U02 06032??	1-1/4"	100	100
U02 06038??	1-1/2"	100	100
U02 06045??	1-3/4"	100	100
U02 06050??	2"	100	100

Continued next page



Continued from previous page

Code	Length	Plain	Zinc
U02 06057??	2-1/4"	100	100
U02 06063??	2-1/2"	100	100
U02 06069??	2-3/4"	100	100
U02 06075??	3"	100	100
U02 06082??	3-1/4"	100	100
U02 06088??	3-1/2"	100	100
U02 06094??	3-3/4"	100	
U02 06100??	4"	100	100
U02 06112??	4-1/2"	50	50
U02 06125??	5"	50	50
U02 06138??	5-1/2"	50	50
U02 06150??	6"	50	50
U02 06163??	6-1/2"	50	
U02 06175??	7"	50	
U02 06200??	8"	50	



Wrench size 3/16

Replace ?? With PL = Plain or ZP = Zinc

5/16 Unc - 18 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 08008??	5/16	100	
U02 08010??	3/8	100	100
U02 08012??	1/2	100	100
U02 08016??	5/8	100	100
U02 08020??	3/4	100	100
U02 08022??	7/8	100	100
U02 08025??	1"	100	100
U02 08028??	1-1/8"	100	
U02 08032??	1-1/4"	100	100
U02 08038??	1-1/2"	100	100
U02 08045??	1-3/4"	100	100
U02 08050??	2"	100	100
U02 08057??	2-1/4"	100	100
U02 08063??	2-1/2"	100	100
U02 08069??	2-3/4"	100	100
U02 08075??	3"	100	100
U02 08082??	3-1/4"	100	
U02 08088??	3-1/2"	100	100
U02 08100??	4"	100	100
U02 08112??	4-1/2"	50	50
U02 08125??	5"	50	50
U02 08138??	5-1/2"	50	50
U02 08150??	6"	50	50
U02 08163??	6-1/2"	50	



Continued next page



Continued from previous page

U02 08175??	7"	50
U02 08200??	8"	50
U02 08225??	9"	50
U02 08250??	10"	50

Wrench size 1/4

Replace ?? With PL = Plain or ZP = Zinc

3/8 Unc - 16 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 10010??	3/8	100	
U02 10012??	1/2	100	100
U02 10016??	5/8	100	100
U02 10020??	3/4	100	100
U02 10022??	7/8	100	100
U02 10025??	1"	100	100
U02 10028??	1-1/8"	100	
U02 10032??	1-1/4"	100	100
U02 10038??	1-1/2"	100	100
U02 10045??	1-3/4"	100	100
U02 10050??	2"	100	100
U02 10057??	2-1/4"	100	100
U02 10063??	2-1/2"	50	50
U02 10069??	2-3/4"	50	50
U02 10075??	3"	50	50
U02 10082??	3-1/4"	50	50
U02 10088??	3-1/2"	50	50
U02 10094??	3-3/4"	50	
U02 10100??	4"	50	50
U02 10106??	4-1/4"	50	
U02 10112??	4-1/2"	50	50
U02 10120??	4-3/4"	50	
U02 10125??	5"	50	50
U02 10138??	5-1/2"	50	50
U02 10150??	6"	50	50
U02 10163??	6-1/2"	25	25
U02 10175??	7"	25	25
U02 10188??	7-1/2"	25	25
U02 10200??	8"	25	25
U02 10225??	9"	1	1
U02 10250??	10"	1	1

Wrench size 5/16

Replace ?? With PL = Plain or ZP = Zinc






7/16 Unc - 14 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 11012??	1/2	100	100
U02 11016??	5/8	100	100
U02 11020??	3/4	100	100
U02 11022??	7/8	100	100
U02 11025??	1"	100	100
U02 11032??	1-1/4"	100	100
U02 11038??	1-1/2"	100	100
U02 11045??	1-3/4"	100	100
U02 11050??	2"	50	50
U02 11057??	2-1/4"	50	50
U02 11063??	2-1/2"	50	50
U02 11069??	2-3/4"	50	50
U02 11075??	3"	50	50
U02 11082??	3-1/4"	50	50
U02 11088??	3-1/2"	50	50
U02 11100??	4"	50	50
U02 11112??	4-1/2"	50	
U02 11125??	5"	25	25
U02 11138??	5-1/2"	25	
U02 11150??	6"	25	25
Wrench size 3/8		Replace ?? With PL = Plain or ZP = Zinc	



1/2 Unc - 13 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 12010??	3/8	50	
U02 12012??	1/2	50	50
U02 12016??	5/8	50	50
U02 12020??	3/4	50	50
U02 12022??	7/8	50	50
U02 12025??	1"	50	50
U02 12028??	1-1/8"	50	50
U02 12032??	1-1/4"	50	50
U02 12038??	1-1/2"	50	50
U02 12045??	1-3/4"	50	50
U02 12050??	2"	50	50
U02 12057??	2-1/4"	50	50
U02 12063??	2-1/2"	50	50
U02 12069??	2-3/4"	50	50
U02 12075??	3"	50	50
U02 12082??	3-1/4"	25	25



Continued next page



Continued from previous page

U02 12088??	3-1/2"	25	25
U02 12094??	3-3/4"	25	
U02 12100??	4"	25	25
U02 12106??	4-1/4"	25	
U02 12112??	4-1/2"	25	25
U02 12120??	4-3/4"	25	
U02 12125??	5"	25	25
U02 12132??	5-1/4"	25	
U02 12138??	5-1/2"	25	25
U02 12150??	6"	25	25
U02 12163??	6-1/2"	10	10
U02 12175??	7"	10	10
U02 12200??	8"	10	10
U02 12212??	8-1/2"	10	
U02 12225??	9"	10	10
U02 12238??	9-1/2"	10	
U02 12250??	10"	1	1
U02 12275??	11"	1	1
U02 12300??	12"	1	1
U02 12350??	14"	1	
U02 12375??	15"	1	
U02 12400??	16"	1	
Wrench size 3/8		Replace ?? With PL = Plain or ZP = Zinc	



5/8 Unc - 11 tpi			
Code	Length	Plain	Zinc
Pack Quantity (if available)			
U02 16016??	5/8	50	
U02 16020??	3/4	50	50
U02 16022??	7/8	50	
U02 16025??	1"	50	50
U02 16028??	1-1/8"	50	
U02 16032??	1-1/4"	50	50
U02 16038??	1-1/2"	50	50
U02 16045??	1-3/4"	50	50
U02 16050??	2"	50	50
U02 16057??	2-1/4"	25	25
U02 16063??	2-1/2"	25	25
U02 16069??	2-3/4"	25	25
U02 16075??	3"	25	25
U02 16082??	3-1/4"	25	25
U02 16088??	3-1/2"	25	25
U02 16094??	3-3/4"	25	
U02 16100??	4"	25	25



Continued next page



Continued from previous page


U02 16106??	4-1/4"	25	
U02 16112??	4-1/2"	25	25
U02 16125??	5"	25	25
U02 16138??	5-1/2"	10	10
U02 16150??	6"	10	10
U02 16163??	6-1/2"	10	10
U02 16175??	7"	10	10
U02 16188??	7-1/2"	10	10
U02 16200??	8"	10	10
U02 16212??	8-1/2"	10	
U02 16225??	9"	10	10
U02 16238??	9-1/2"	1	
U02 16250??	10"	1	1
U02 16275??	11"	1	1
U02 16300??	12"	1	1
U02 16350??	14"	1	1
U02 16375??	15"	1	1
U02 16400??	16"	1	

Wrench size 1/2

Replace ?? With PL = Plain or ZP = Zinc

3/4 Unc - 10 tpi

Code	Length	Pack Quantity (if available)	
		Plain	Zinc
U02 20025??	1"	25	25
U02 20032??	1-1/4"	25	25
U02 20038??	1-1/2"	25	25
U02 20045??	1-3/4"	25	25
U02 20050??	2"	25	25
U02 20057??	2-1/4"	25	25
U02 20063??	2-1/2"	25	25
U02 20069??	2-3/4"	25	25
U02 20075??	3"	25	25
U02 20082??	3-1/4"	25	25
U02 20088??	3-1/2"	25	25
U02 20094??	3-3/4"	25	
U02 20100??	4"	25	25
U02 20106??	4-1/4"	25	
U02 20112??	4-1/2"	25	25
U02 20120??	4-3/4"	25	
U02 20125??	5"	25	25
U02 20138??	5-1/2"	10	10
U02 20150??	6"	10	10
U02 20163??	6-1/2"	10	10
U02 20175??	7"	10	10



Continued next page



Continued from previous page

Code	Length	Plain	Zinc
U02 20188??	7-1/2"	10	10
U02 20200??	8"	10	10
U02 20212??	8-1/2"	1	1
U02 20225??	9"	1	1
U02 20250??	10"	1	1
U02 20275??	11"	1	1
U02 20300??	12"	1	1
U02 20325??	13"	1	1
U02 20350??	14"	1	1
U02 20375??	15"	1	
U02 20400??	16"	1	
U02 20450??	18"	1	
U02 20500??	20"	1	


Wrench size 5/8

Replace ?? With PL = Plain or ZP = Zinc

7/8 Unc - 9 tpi

Code	Length	Plain	Zinc
U02 22032??	1-1/4"	10	
U02 22038??	1-1/2"	10	10
U02 22045??	1-3/4"	10	10
U02 22050??	2"	10	10
U02 22057??	2-1/4"	10	10
U02 22063??	2-1/2"	10	10
U02 22069??	2-3/4"	10	10
U02 22075??	3"	10	10
U02 22082??	3-1/4"	10	10
U02 22088??	3-1/2"	10	10
U02 22100??	4"	10	10
U02 22112??	4-1/2"	10	10
U02 22120??	4-3/4"	10	
U02 22125??	5"	10	10
U02 22138??	5-1/2"	10	
U02 22150??	6"	10	10
U02 22163??	6-1/2"	10	
U02 22175??	7"	10	10
U02 22188??	7-1/2"	10	10
U02 22200??	8"	10	10
U02 22225??	9"	1	1
U02 22250??	10"	1	1
U02 22275??	11"	1	1
U02 22300??	12"	1	1
U02 22350??	14"	1	
U02 22400??	16"	1	

Pack Quantity (if available)



Wrench size 3/4

Replace ?? With PL = Plain or ZP = Zinc



1" Unc - 8 tpi				
Code	Length	Plain	Zinc	Pack Quantity (if available)
U02 25038??	1-1/2"	10	10	
U02 25045??	1-3/4"	10	10	
U02 25050??	2"	10	10	
U02 25057??	2-1/4"	10	10	
U02 25063??	2-1/2"	10	10	
U02 25069??	2-3/4"	10	10	
U02 25075??	3"	10	10	
U02 25082??	3-1/4"	10	10	
U02 25088??	3-1/2"	10	10	
U02 25094??	3-3/4"	10	10	
U02 25100??	4"	10	10	
U02 25106??	4-1/4"	10	10	
U02 25112??	4-1/2"	10	10	
U02 25120??	4-3/4"	10	10	
U02 25125??	5"	10	10	
U02 25138??	5-1/2"	10	10	
U02 25150??	6"	10	10	
U02 25163??	6-1/2"	10	10	
U02 25175??	7"	10	10	
U02 25188??	7-1/2"	10	10	
U02 25200??	8"	10	10	
U02 25212??	8-1/2"	1		
U02 25225??	9"	1	1	
U02 25238??	9-1/2"	1	1	
U02 25250??	10"	1	1	
U02 25263??	10-1/2"	1		
U02 25275??	11"	1	1	
U02 25300??	12"	1	1	
U02 25325??	13"	1	1	
U02 25350??	14"	1	1	
U02 25400??	16"	1		
U02 25450??	18"	1		
U02 25500??	20"	1		



Wrench size 3/4

Replace ?? With PL = Plain or ZP = Zinc

Larger sizes available - Contact the office to enquire