



## Hexagon Standard Nut

### Metric

Size	Code	ZP	H.D. Gal	Plain
Pack Quantity (if available)				
M2.5 x 0.45p	N01 025??	200		
M3 x 0.5p	N01 03??	200		
M4 x 0.7p	N01 04??	200		
M5 x 0.8p	N01 05??	200		
M6 x 1.0p	N01 06??	200	1000	
M8 x 1.25p	N01 08??	200	500	
M10 x 1.5p	N01 10??	200	200	
M12 x 1.75p	N01 12??	100	200	
M16 x 2.0p	N01 16??	75	200	200
M20 x 2.5p	N01 20??	75	100	100
M24 x 3.0p	N01 24??	50	100	100
M27 x 3.0p	N01 27??	30	75	75
M30 x 3.5p	N01 30??	30	50	50
M33 x 3.5p	N01 33??	25	50	50
M36 x 4.0p	N01 36??	10	25	25
M42 x 5.5p	N01 42??	10	20	20



Replace ?? With ZP = Zinc Plated, GA = H.D. Gal, PL = Plain

### BSW

Size	Code	ZP	H.D. Gal	Plain
Pack Quantity (if available)				
1/8	N00 03??	200		
5/32	N00 04??	200		
3/16	N00 05??	200		
1/4	N00 06??	200		200
5/16	N00 08??	200		200
3/8	N00 10??	200		200
7/16	N00 11??	200		
1/2	N00 12??	200		150
9/16	N00 14??	75		
5/8	N00 16??	75		75
3/4	N00 20??	50		250
7/8	N00 22??	30		200
1"	N00 25??	30		150

Replace ?? With ZP = Zinc Plated, GA = H.D. Gal, PL = Plain



## Hexagon Standard Nut

### UNC

Size	Code	ZP	H.D. Gal	Plain
Pack Quantity (if available)				
3/16	N02 05??	200		
1/4	N02 06??	200		200
5/16	N02 08??	200		200
3/8	N02 10??	200		200
7/16	N02 11??	200		200
1/2	N02 12??	200		200
9/16	N02 14??	75		75
5/8	N02 16??	75		75
3/4	N02 20??	75		75
7/8	N02 22??	50		50
1"	N02 25??	50		50
1-1/8"	N02 28??	25		25
1-1/4"	N02 32??	25		25
1-1/2"	N02 38??	15		15



Replace ?? With ZP = Zinc Plated, GA = H.D. Gal, PL = Plain

### UNF

Size	Code	ZP	H.D. Gal	Plain
Pack Quantity (if available)				
3/16	N03 05??	200		
1/4	N03 06??	200		200
5/16	N03 08??	200		200
3/8	N03 10??	200		200
7/16	N03 11??	200		200
1/2	N03 12??	200		200
9/16	N03 14??	75		75
5/8	N03 16??	75		75
3/4	N03 20??	75		75
7/8	N03 22??	50		50
1"	N03 25??	50		50

Replace ?? With ZP = Zinc Plated, GA = H.D. Gal, PL = Plain