



## Cheese Head Machine Screw - Metric - Stainless

### M3 x 0.5p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
6mm	X37 0306CHS???	200	200
8mm	X37 0308CHS???	200	200
10mm	X37 0310CHS???	200	200
12mm	X37 0312CHS???	200	200
16mm	X37 0316CHS???	200	200
20mm	X37 0320CHS???	200	200
25mm	X37 0325CHS???	200	200
30mm	X37 0330CHS???	200	
35mm	X37 0335CHS???		200
40mm	X37 0340CHS???	200	
50mm	X37 0350CHS???	200	



Replace ??? With 304 or 316

### M4 x 0.7p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
6mm	X37 0406CHS???	200	200
8mm	X37 0408CHS???	200	200
10mm	X37 0410CHS???	200	200
12mm	X37 0412CHS???	200	200
16mm	X37 0416CHS???	200	200
20mm	X37 0420CHS???	200	200
25mm	X37 0425CHS???	200	200
30mm	X37 0430CHS???	200	
40mm	X37 0440CHS???	200	200
50mm	X37 0450CHS???	200	200
80mm	X37 0480CHS???		200

Replace ??? With 304 or 316

### M5 x 0.8p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
6mm	X37 0506CHS???	100	
8mm	X37 0508CHS???	100	
10mm	X37 0510CHS???	100	100
12mm	X37 0512CHS???	100	100
16mm	X37 0516CHS???	100	100
20mm	X37 0520CHS???	100	100
25mm	X37 0525CHS???	100	100

Replace ??? With 304 or 316

Continued next page



## Cheese Head Machine Screw - Metric - Stainless

Continued from previous page

### M5 x 0.8p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
30mm	X37 0530CHS???	100	100
35mm	X37 0535CHS???	100	
40mm	X37 0540CHS???	100	100
50mm	X37 0550CHS???	100	100
60mm	X37 0560CHS???	100	100
70mm	X37 0570CHS???	100	100
80mm	X37 0580CHS???	100	100
90mm	X37 0590CHS???		100
Replace ??? With 304 or 316			



### M6 x 1.0p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
10mm	X37 0610CHS???	100	100
12mm	X37 0612CHS???	100	100
16mm	X37 0616CHS???	100	100
20mm	X37 0620CHS???	100	100
25mm	X37 0625CHS???	100	100
30mm	X37 0630CHS???	100	100
35mm	X37 0635CHS???	100	100
40mm	X37 0640CHS???	100	100
50mm	X37 0650CHS???	100	100
60mm	X37 0660CHS???	50	50
70mm	X37 0670CHS???	50	50
80mm	X37 0680CHS???	50	50
90mm	X37 0690CHS???		50
100mm	X37 0699CHS???	50	50
Replace ??? With 304 or 316			

### M8 x 1.25p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
12mm	X37 0812CHS???	100	100
16mm	X37 0816CHS???	100	100
20mm	X37 0820CHS???	100	100
25mm	X37 0825CHS???	100	100
30mm	X37 0830CHS???	100	100
35mm	X37 0835CHS???		100
Replace ??? With 304 or 316			

Continued next page



## Cheese Head Machine Screw - Metric - Stainless

Continued from previous page

### M8 x 1.25p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
40mm	X37 0840CHS???	100	100
50mm	X37 0850CHS???	100	100
Replace ??? With 304 or 316			



### M10 x 1.5p (Slot)

Size	Code	Gr 304 / A2	Gr 316 / A4
<b>Pack Quantity (if available)</b>			
20mm	X37 1020CHS???	100	50
25mm	X37 1025CHS???	100	50
30mm	X37 1030CHS???		50
35mm	X37 1035CHS???		50
40mm	X37 1040CHS???	100	50
50mm	X37 1050CHS???	100	50
Replace ??? With 304 or 316			