



Socket Set (Grub) Screw - Cup point - Metric - Gr 14.9

M3 x 0.5p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3mm	U10 0303??	100	
4mm	U10 0304??	100	
5mm	U10 0305??	100	
6mm	U10 0306??	100	
8mm	U10 0308??	100	
10mm	U10 0310??	100	
12mm	U10 0312??	100	
16mm	U10 0316??	100	
20mm	U10 0320??	100	
25mm	U10 0325??	100	
30mm	U10 0330??	100	



Wrench size 1.5mm

Replace ?? With PL = Plain or ZP = Zinc

M4 x 0.7p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
4mm	U10 0404??	100	100
5mm	U10 0405??	100	100
6mm	U10 0406??	100	100
8mm	U10 0408??	100	100
10mm	U10 0410??	100	100
12mm	U10 0412??	100	100
16mm	U10 0416??	100	
20mm	U10 0420??	100	
25mm	U10 0425??	100	
30mm	U10 0430??	100	
35mm	U10 0435??		

Wrench size 2mm

Replace ?? With PL = Plain or ZP = Zinc

M5 x 0.8p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
5mm	U10 0505??	100	100
6mm	U10 0506??	100	100
8mm	U10 0508??	100	100
10mm	U10 0510??	100	100
12mm	U10 0512??	100	100
16mm	U10 0516??	100	100
20mm	U10 0520??	100	100

Wrench size 2.5mm

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



Socket Set (Grub) Screw - Cup point - Metric - Gr 14.9

Continued from previous page

M5 x 0.8p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
25mm	U10 0525??	100	100
30mm	U10 0530??	100	100
35mm	U10 0535??	100	
40mm	U10 0540??	100	
45mm	U10 0545??	100	
50mm	U10 0550??	100	
Wrench size 2.5mm		Replace ?? With PL = Plain or ZP = Zinc	



M6 x 1.0p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
5mm	U10 0605??	100	100
6mm	U10 0606??	100	100
8mm	U10 0608??	100	100
10mm	U10 0610??	100	100
12mm	U10 0612??	100	100
16mm	U10 0616??	100	100
20mm	U10 0620??	100	100
25mm	U10 0625??	100	100
30mm	U10 0630??	100	100
35mm	U10 0635??	100	100
40mm	U10 0640??	100	100
45mm	U10 0645??	100	100
50mm	U10 0650??	100	100
Wrench size 3mm		Replace ?? With PL = Plain or ZP = Zinc	

M8 x 1.25p

Length	Code	Plain	Zinc
Pack Quantity (if available)			
6mm	U10 0806??	100	100
8mm	U10 0808??	100	100
10mm	U10 0810??	100	100
12mm	U10 0812??	100	100
16mm	U10 0816??	100	100
20mm	U10 0820??	100	100
25mm	U10 0825??	100	100
30mm	U10 0830??	100	100
35mm	U10 0835??	100	100
Wrench size 4mm		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



Socket Set (Grub) Screw - Cup point - Metric - Gr 14.9

Continued from previous page

M8 x 1.25p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
40mm	U10 0840??	100	100
45mm	U10 0845??	100	100
50mm	U10 0850??	100	100
60mm	U10 0860??	100	100
70mm	U10 0870??	100	
80mm	U10 0880??	100	
90mm	U10 0890??	100	
100mm	U10 0899??	100	
Wrench size 4mm		Replace ?? With PL = Plain or ZP = Zinc	



M10 x 1.5p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
8mm	U10 1008??	100	
10mm	U10 1010??	100	100
12mm	U10 1012??	100	100
16mm	U10 1016??	100	100
20mm	U10 1020??	100	100
25mm	U10 1025??	100	100
30mm	U10 1030??	100	100
35mm	U10 1035??	100	100
40mm	U10 1040??	100	100
45mm	U10 1045??	50	
50mm	U10 1050??	50	
55mm	U10 1055??	50	
60mm	U10 1060??	50	
70mm	U10 1070??	50	
80mm	U10 1080??	50	
90mm	U10 1090??	50	
100mm	U10 1099??	50	
Wrench size 5mm		Replace ?? With PL = Plain or ZP = Zinc	

M12 x 1.75p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
12mm	U10 1212??	100	100
16mm	U10 1216??	100	100
20mm	U10 1220??	100	100
Wrench size 6mm		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



Socket Set (Grub) Screw - Cup point - Metric - Gr 14.9

Continued from previous page

M12 x 1.75p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
25mm	U10 1225??	100	100
30mm	U10 1230??	100	100
35mm	U10 1235??	100	
40mm	U10 1240??	50	
45mm	U10 1245??	50	
50mm	U10 1250??	50	
55mm	U10 1255??	50	
60mm	U10 1260??	50	
65mm	U10 1265??	50	
70mm	U10 1270??	50	
80mm	U10 1280??	50	
90mm	U10 1290??	50	
100mm	U10 1299??	50	



Wrench size 6mm

Replace ?? With PL = Plain or ZP = Zinc

M14 x 2.0p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
16mm	U10 1416??	50	
20mm	U10 1420??	50	
25mm	U10 1425??	50	
30mm	U10 1430??	50	
35mm	U10 1435??	50	
40mm	U10 1440??	50	
50mm	U10 1450??	50	

Wrench size 6mm

Replace ?? With PL = Plain or ZP = Zinc

M16 x 2.0p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
16mm	U10 1616??	50	50
20mm	U10 1620??	50	50
25mm	U10 1625??	50	50
30mm	U10 1630??	50	50
35mm	U10 1635??	50	50
40mm	U10 1640??	50	50
45mm	U10 1645??	50	50
50mm	U10 1650??	50	50

Wrench size 8mm

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



Socket Set (Grub) Screw - Cup point - Metric - Gr 14.9

Continued from previous page

M16 x 2.0p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
55mm	U10 1655??	25	25
60mm	U10 1660??	25	25
70mm	U10 1670??	25	25
80mm	U10 1680??	25	
90mm	U10 1690??	25	
100mm	U10 1699??	25	
Wrench size 8mm		Replace ?? With PL = Plain or ZP = Zinc	



M20 x 2.5p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
20mm	U10 2020??	50	
25mm	U10 2025??	50	
30mm	U10 2030??	50	
35mm	U10 2035??	50	
40mm	U10 2040??	50	
45mm	U10 2045??	25	
50mm	U10 2050??	25	
55mm	U10 2055??	25	
60mm	U10 2060??	25	
65mm	U10 2065??	25	
70mm	U10 2070??	25	
80mm	U10 2080??	25	
90mm	U10 2090??	25	
100mm	U10 2099??	25	
Wrench size 10mm		Replace ?? With PL = Plain or ZP = Zinc	

M24 x 3.0p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
25mm	U10 2425??	50	
30mm	U10 2430??	50	
35mm	U10 2435??	50	
40mm	U10 2440??	25	
45mm	U10 2445??	25	
50mm	U10 2450??	25	
55mm	U10 2455??	25	
60mm	U10 2460??	25	
Wrench size 12mm		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



Socket Set (Grub) Screw - Cup point - Metric - Gr 14.9

Continued from previous page

M24 x 3.0p

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
70mm	U10 2470??	25	
80mm	U10 2480??	25	
90mm	U10 2490??	25	
100mm	U10 2499??	25	
Wrench size 12mm		Replace ?? With PL = Plain or ZP = Zinc	

