


Eye Bolt with Nut & Washer



1/4 BSW

Size (L)	Code	Y	T	ZP	H.D. Gal
Pack Quantity (if available)					
2"	B57 06050??	3/8"	1-1/2"	100	
2-1/2"	B57 06063??	3/8"	1-1/2"	100	
3"	B57 06075??	3/8"	1-1/2"	100	
4"	B57 06100??	3/8"	1-1/2"	100	
4-1/2"	B57 06112??	3/8"	1-1/2"	100	

5/16 BSW


Size (L)	Code	Y	T	ZP	H.D. Gal
Pack Quantity (if available)					
2"	B57 08050??	1/2"	1-1/2"	100	
2-1/2"	B57 08063??	1/2"	1-1/2"	100	
3"	B57 08075??	1/2"	1-1/2"	100	
4"	B57 08100??	1/2"	1-1/2"	100	
4-1/2"	B57 08112??	1/2"	1-1/2"	100	
5"	B57 08125??	1/2"	1-1/2"	100	
6"	B57 08150??	1/2"	1-1/2"	100	

3/8 BSW

Size (L)	Code	Y	T	ZP	H.D. Gal
Pack Quantity (if available)					
2"	B57 10050??	3/4"	1-1/2"		50
3"	B57 10075??	3/4"	1-1/2"		50
3-1/2"	B57 10088??	3/4"	1-1/2"		50
4"	B57 10100??	3/4"	1-1/2"		50
6"	B57 10150??	3/4"	1-1/2"		50
8"	B57 10200??	3/4"	2-1/4"		25
12"	B57 10300??	3/4"	3"		25

Replace ?? With ZP = Zinc Plated, GA = H.D. Gal

Eye Bolt with Nut & Washer



1/2 BSW


Size (L)	Code	Y	T	ZP	H.D. Gal
Pack Quantity (if available)					
3"	B57 12075??	3/4"	2-1/2"		25
4"	B57 12100??	3/4"	2-1/2"		25
5"	B57 12125??	3/4"	2-1/2"		25
6"	B57 12150??	3/4"	2-1/2"		25
8"	B57 12200??	3/4"	2-1/2"		25
9"	B57 12225??	3/4"	2-1/2"		25

5/8 BSW

Size (L)	Code	Y	T	ZP	H.D. Gal
Pack Quantity (if available)					
4"	B57 16100??	1"	2-1/2"		25

Replace ?? With ZP = Zinc Plated, GA = H.D. Gal


Hook Bolt with Nut



1/4 BSW (A)

Size (L)	Code	T	E	D	ZP
Pack Quantity					
1"	B73 06025ZP	1/2"	45°	3/4"	100
1-1/2"	B73 06038ZP	1"	45°	3/4"	100
2"	B73 06050ZP	1-1/2"	45°	3/4"	100
2-1/2"	B73 06063ZP	1-1/2"	45°	3/4"	100
3"	B73 06075ZP	1-1/2"	45°	3/4"	100
3-1/2"	B73 06088ZP	1-1/2"	45°	3/4"	100
4"	B73 06100ZP	1-1/2"	45°	3/4"	100
4-1/2"	B73 06112ZP	1-1/2"	45°	3/4"	100
5"	B73 06125ZP	1-1/2"	45°	3/4"	100
6"	B73 06150ZP	1-1/2"	45°	3/4"	50
8"	B73 06200ZP	1-1/2"	45°	3/4"	50

J Bolt with Nut



1/4 BSW (A)

Nominal Bore	Code	W	L	T	D	ZP	Pack Qty
1/2"	B72 06012ZP	7/8"	2-3/8"	1-1/2"	3/4"		100
3/4"	B72 06020ZP	1-1/16"	2-3/4"	1-1/2"	3/4"		100
1"	B72 06025ZP	1-3/8"	2-7/8"	1-1/2"	1-1/8"		100
1-1/4"	B72 06032ZP	1-11/16"	3-1/4"	1-1/2"	1-3/8"		100
1-1/2"	B72 06038ZP	1-15/16"	3-3/4"	1-1/2"	1-1/2"		100
1-3/4"	B72 06045ZP	2-5/32"	4-1/8"	1-1/2"	1-5/8"		100
2"	B72 06050ZP	2-3/8"	4-3/8"	1-1/2"	1-7/8"		100


Furniture Lag Screw

1/4 BSW (A)

Size (L)	Code	M	W	ZP	Pack Quantity
2"	F00 06050ZP	1/2"	45°		100
2-1/2"	F00 06063ZP	1"	45°		100
3"	F00 06075ZP	1-1/2"	45°		100

5/16 BSW (A)

Size (L)	Code	M	W	ZP	Pack Quantity
1-3/4"	F00 08045ZP	5/8"	1-1/8"		100
2"	F00 08050ZP	7/8"	1-1/8"		100
2-1/2"	F00 08063ZP	1"	1-1/2"		100
2-3/4"	F00 08069ZP	1-1/4"	1-1/2"		100
3"	F00 08075ZP	1-1/2"	1-1/2"		100
3-1/2"	F00 08088ZP	1-1/4"	1-1/2"		100



1/2 BSW (A)

Size (L)	Code	M	W	ZP	Pack Quantity
6"	F00 12150ZP	1-1/4"	4-1/2"		100