



Flat Head Socket Screw - UNC - Alloy Steel

#10 Unc - 24 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1/4	U20 05006??	100	100
5/16	U20 05008??	100	100
3/8	U20 05010??	100	100
1/2	U20 05012??	100	100
5/8	U20 05016??	100	100
3/4	U20 05020??	100	100
7/8	U20 05022??	100	
1"	U20 05025??	100	100
1-1/4"	U20 05032??	100	100
1-1/2"	U20 05038??	100	100
1-3/4"	U20 05045??	100	100
2"	U20 05050??	100	100
2-1/4"	U20 05057??	100	
2-1/2"	U20 05063??	100	100
3"	U20 05075??	100	100



Wrench size 1/8

Replace ?? With PL = Plain or ZP = Zinc

1/4 Unc - 20 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3/8	U20 06010??	100	100
1/2	U20 06012??	100	100
5/8	U20 06016??	100	100
3/4	U20 06020??	100	100
7/8	U20 06022??	100	
1"	U20 06025??	100	100
1-1/8"	U20 06028??	100	
1-1/4"	U20 06032??	100	100
1-1/2"	U20 06038??	100	100
1-3/4"	U20 06045??	100	100
2"	U20 06050??	100	100
2-1/4"	U20 06057??	100	
2-1/2"	U20 06063??	100	100
2-3/4"	U20 06069??	100	
3"	U20 06075??	100	100
3-1/2"	U20 06088??	100	100
4"	U20 06100??	100	100

Wrench size 5/32

Replace ?? With PL = Plain or ZP = Zinc



Flat Head Socket Screw - UNC - Alloy Steel

5/16 Unc - 18 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3/8	U20 08010??	100	
1/2	U20 08012??	100	100
5/8	U20 08016??	100	100
3/4	U20 08020??	100	100
7/8	U20 08022??	100	
1"	U20 08025??	100	100
1-1/8"	U20 08028??	100	
1-1/4"	U20 08032??	100	100
1-1/2"	U20 08038??	100	100
1-3/4"	U20 08045??	100	100
2"	U20 08050??	100	100
2-1/4"	U20 08057??	100	100
2-1/2"	U20 08063??	100	100
2-3/4"	U20 08069??	100	
3"	U20 08075??	100	100
3-1/2"	U20 08088??	100	100
3-3/4"	U20 08094??	100	
4"	U20 08100??	100	100
Wrench size 3/16		Replace ?? With PL = Plain or ZP = Zinc	



3/8 Unc - 16 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3/8	U20 10010??	100	
1/2	U20 10012??	100	100
5/8	U20 10016??	100	100
3/4	U20 10020??	100	100
7/8	U20 10022??	100	
1"	U20 10025??	100	100
1-1/8"	U20 10028??	100	
1-1/4"	U20 10032??	100	100
1-1/2"	U20 10038??	100	100
1-3/4"	U20 10045??	100	100
2"	U20 10050??	100	100
2-1/4"	U20 10057??	100	100
2-1/2"	U20 10063??	50	50
2-3/4"	U20 10069??	50	50
3"	U20 10075??	50	50
3-1/2"	U20 10088??	50	50
Wrench size 7/32		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



Flat Head Socket Screw - UNC - Alloy Steel

Continued from previous page

3/8 Unc - 16 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
4"	U20 10100??	50	50
4-1/2"	U20 10112??	50	
5"	U20 10125??	50	
5-1/2"	U20 10138??	50	
6"	U20 10150??	50	



Wrench size 7/32

Replace ?? With PL = Plain or ZP = Zinc

7/16 Unc - 14 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
3/4	U20 11020??	100	100
7/8	U20 11022??	100	
1"	U20 11025??	100	100
1-1/4"	U20 11032??	100	100
1-1/2"	U20 11038??	100	100
1-3/4"	U20 11045??	100	100
2"	U20 11050??	50	50
2-1/4"	U20 11057??	50	
2-1/2"	U20 11063??	50	
3"	U20 11075??	50	
3-1/2"	U20 11088??	50	
4"	U20 11100??	50	

Wrench size 1/4

Replace ?? With PL = Plain or ZP = Zinc

1/2 Unc - 13 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
3/4	U20 12020??	50	50
7/8	U20 12022??	50	
1"	U20 12025??	50	50
1-1/4"	U20 12032??	50	50
1-1/2"	U20 12038??	50	50
1-3/4"	U20 12045??	50	50
2"	U20 12050??	50	50
2-1/4"	U20 12057??	50	50
2-1/2"	U20 12063??	50	50
2-3/4"	U20 12069??	50	
3"	U20 12075??	50	50

Wrench size 5/16

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



Flat Head Socket Screw - UNC - Alloy Steel

Continued from previous page

1/2 Unc - 13 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3-1/4"	U20 12082??	25	
3-1/2"	U20 12088??	25	25
4"	U20 12100??	25	25
4-1/2"	U20 12112??	25	
5"	U20 12125??	25	25
6"	U20 12150??	25	25
7"	U20 12175??	10	
8"	U20 12200??	10	
Wrench size 5/16		Replace ?? With PL = Plain or ZP = Zinc	



5/8 Unc - 11 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1"	U20 16025??	50	50
1-1/4"	U20 16032??	50	50
1-1/2"	U20 16038??	50	50
1-3/4"	U20 16045??	50	50
2"	U20 16050??	50	50
2-1/4"	U20 16057??	25	25
2-1/2"	U20 16063??	25	25
2-3/4"	U20 16069??	25	
3"	U20 16075??	25	25
3-1/2"	U20 16088??	25	25
4"	U20 16100??	10	10
4-1/2"	U20 16112??	10	10
5"	U20 16125??	10	10
5-1/2"	U20 16138??	10	
6"	U20 16150??	10	10
6-1/2"	U20 16163??	10	
7"	U20 16175??	10	
8"	U20 16200??	10	
Wrench size 3/8		Replace ?? With PL = Plain or ZP = Zinc	

3/4 Unc - 10 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1"	U20 20025??	25	
1-1/4"	U20 20032??	25	25
Wrench size 1/2		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



Flat Head Socket Screw - UNC - Alloy Steel

Continued from previous page

3/4 Unc - 10 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
1-1/2"	U20 20038??	25	25
1-3/4"	U20 20045??	25	25
2"	U20 20050??	25	25
2-1/4"	U20 20057??	25	25
2-1/2"	U20 20063??	25	25
2-3/4"	U20 20069??	25	
3"	U20 20075??	25	25
3-1/4"	U20 20082??	25	
3-1/2"	U20 20088??	25	25
4"	U20 20100??	25	25
4-1/2"	U20 20112??	25	
5"	U20 20125??	25	25
6"	U20 20150??	10	10
6-1/2"	U20 20163??	10	
7"	U20 20175??	10	
8"	U20 20200??	10	
Wrench size 1/2		Replace ?? With PL = Plain or ZP = Zinc	



7/8 Unc - 9 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
2"	U20 22050??	10	
2-1/2"	U20 22063??	10	
3"	U20 22075??	10	
3-1/2"	U20 22088??	10	
4"	U20 22100??	10	
4-1/2"	U20 22112??	10	
5"	U20 22125??	10	
6"	U20 22150??	10	
6-1/2"	U20 22163??	10	
7"	U20 22175??	10	
8"	U20 22200??	10	
Wrench size 9/16		Replace ?? With PL = Plain or ZP = Zinc	

1" Unc - 8 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
2"	U20 25050??	10	
Wrench size 5/8		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



Flat Head Socket Screw - UNC - Alloy Steel

Continued from previous page

1" Unc - 8 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
2-1/4"	U20 25057??	10	
2-1/2"	U20 25063??	10	
2-3/4"	U20 25069??	10	
3"	U20 25075??	10	
3-1/2"	U20 25088??	10	
4"	U20 25100??	10	
4-1/2"	U20 25112??	10	
5"	U20 25125??	10	
6"	U20 25150??	10	
6-1/2"	U20 25163??	10	
7"	U20 25175??	10	
8"	U20 25200??	10	
Wrench size 5/8		Replace ?? With PL = Plain or ZP = Zinc	



1-1/4" Unc - 7 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
3"	U02 32075??	1	
3-1/2"	U02 32088??	1	
4"	U02 32100??	1	
5"	U02 32125??	1	
6"	U02 32150??	1	
7"	U02 32175??	1	
8"	U02 32200??	1	
Wrench size 7/8		Replace ?? With PL = Plain or ZP = Zinc	