



UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

#10 Unc - 24 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1/8	U12 05003??	100	
3/16	U12 05005??	100	100
1/4	U12 05006??	100	100
5/16	U12 05008??	100	100
3/8	U12 05010??	100	100
7/16	U12 05011??	100	100
1/2	U12 05012??	100	100
9/16	U12 05014??	100	
5/8	U12 05016??	100	100
3/4	U12 05020??	100	100
7/8	U12 05022??	100	100
1"	U12 05025??	100	100
1-1/8"	U12 05028??	100	
1-1/4"	U12 05032??	100	100
1-1/2"	U12 05038??	100	100
1-3/4"	U12 05045??	100	
2"	U12 05050??	100	
2-1/2"	U12 05063??	100	
3"	U12 05075??	100	



Wrench size 3/32

Replace ?? With PL = Plain or ZP = Zinc

1/4 Unc - 20 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3/16	U12 06005??	100	100
1/4	U12 06006??	100	100
5/16	U12 06008??	100	100
3/8	U12 06010??	100	100
7/16	U12 06011??	100	100
1/2	U12 06012??	100	100
9/16	U12 06014??	100	
5/8	U12 06016??	100	100
3/4	U12 06020??	100	100
7/8	U12 06022??	100	100
1"	U12 06025??	100	100
1-1/8"	U12 06028??	100	100
1-1/4"	U12 06032??	100	100
1-1/2"	U12 06038??	100	100
1-3/4"	U12 06045??	100	100

Wrench size 1/8

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

Continued from previous page

1/4 Unc - 20 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
2"	U12 06050??	100	100
2-1/4"	U12 06057??	100	
2-1/2"	U12 06063??	100	
2-3/4"	U12 06069??	100	
3"	U12 06075??	100	



Wrench size 1/8

Replace ?? With PL = Plain or ZP = Zinc

5/16 Unc - 18 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1/4	U12 08006??	100	100
5/16	U12 08008??	100	100
3/8	U12 08010??	100	100
7/16	U12 08011??	100	100
1/2	U12 08012??	100	100
5/8	U12 08016??	100	100
3/4	U12 08020??	100	100
7/8	U12 08022??	100	100
1"	U12 08025??	100	100
1-1/4"	U12 08032??	100	100
1-1/2"	U12 08038??	100	100
1-3/4"	U12 08045??	100	100
2"	U12 08050??	100	100
2-1/4"	U12 08057??	100	
2-1/2"	U12 08063??	100	
2-3/4"	U12 08069??	100	
3"	U12 08075??	100	

Wrench size 5/32

Replace ?? With PL = Plain or ZP = Zinc

3/8 Unc - 16 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1/4	U12 10006??	100	100
5/16	U12 10008??	100	100
3/8	U12 10010??	100	100
7/16	U12 100011?	100	100
1/2	U12 10012??	100	100
5/8	U12 10016??	100	100

Wrench size 3/16

Replace ?? With PL = Plain or ZP = Zinc

Continued next page



UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

Continued from previous page

3/8 Unc - 16 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
3/4	U12 10020??	100	100
7/8	U12 10022??	100	100
1"	U12 10025??	100	100
1-1/4"	U12 10032??	100	100
1-1/2"	U12 10038??	100	100
1-3/4"	U12 10045??	100	100
2"	U12 10050??	100	100
2-1/4"	U12 10057??	100	100
2-1/2"	U12 10063??	100	100
2-3/4"	U12 10069??	100	
3"	U12 10075??	100	
3-1/2"	U12 10088??	100	
4"	U12 10100??	100	



Wrench size 3/16

Replace ?? With PL = Plain or ZP = Zinc

7/16 Unc - 14 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
3/8	U12 11010??	100	100
7/16	U12 11011??	100	100
1/2	U12 11012??	100	100
5/8	U12 11016??	100	100
3/4	U12 11020??	100	100
7/8	U12 11022??	100	100
1"	U12 11025??	100	100
1-1/4"	U12 11032??	100	100
1-1/2"	U12 11038??	100	100
1-3/4"	U12 11045??	100	100
2"	U12 11050??	100	100
2-1/4"	U12 11057??	100	
2-1/2"	U12 11063??	100	
2-3/4"	U12 11069??	100	
3"	U12 11075??	100	
4"	U12 11100??	50	

Wrench size 7/32

Replace ?? With PL = Plain or ZP = Zinc



UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

1/2 Unc - 13 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
3/8	U12 12010??	100	100
7/16	U12 12011??	100	100
1/2	U12 12012??	100	100
5/8	U12 12016??	100	100
3/4	U12 12020??	100	100
7/8	U12 12022??	100	100
1"	U12 12025??	100	100
1-1/4"	U12 12032??	100	100
1-1/2"	U12 12038??	100	100
1-3/4"	U12 12045??	50	50
2"	U12 12050??	50	50
2-1/4"	U12 12057??	50	
2-1/2"	U12 12063??	50	50
2-3/4"	U12 12069??	50	
3"	U12 12075??	50	50
3-1/4"	U12 12082??	50	
3-1/2"	U12 12088??	50	
4"	U12 12100??	50	
4-1/2"	U12 12112??	50	
5"	U12 12125??	50	
5-1/2"	U12 12138??	25	
6"	U12 12150??	25	
Wrench size 1/4		Replace ?? With PL = Plain or ZP = Zinc	



5/8 Unc - 11 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1/2	U12 16012??	50	
5/8	U12 16016??	50	
3/4	U12 16020??	50	
7/8	U12 16022??	50	
1"	U12 16025??	50	
1-1/4"	U12 16032??	50	
1-1/2"	U12 16038??	50	
1-3/4"	U12 16045??	50	
2"	U12 16050??	50	
2-1/4"	U12 16057??	50	
2-1/2"	U12 16063??	50	
2-3/4"	U12 16069??	50	
Wrench size 5/16		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page



UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

Continued from previous page

5/8 Unc - 11 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
3"	U12 16075??	50	
3-1/4"	U12 16082??	25	
3-1/2"	U12 16088??	25	
4"	U12 16100??	25	
4-1/2"	U12 16112??	25	
5"	U12 16125??	25	
5-1/2"	U12 16138??	25	
6"	U12 16150??	25	
Wrench size 5/16		Replace ?? With PL = Plain or ZP = Zinc	



3/4 Unc - 10 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
5/8	U12 20016??	50	
3/4	U12 20020??	50	
7/8	U12 20022??	50	
1"	U12 20025??	50	
1-1/4"	U12 20032??	50	
1-1/2"	U12 20038??	50	
1-3/4"	U12 20045??	25	
2"	U12 20050??	25	
2-1/4"	U12 20057??	25	
2-1/2"	U12 20063??	25	
3"	U12 20075??	25	
3-1/4"	U12 20082??	25	
3-1/2"	U12 20088??	25	
4"	U12 20100??	25	
4-1/2"	U12 20112??	10	
5"	U12 20125??	10	
5-1/2"	U12 20138??	10	
6"	U12 20150??	10	
Wrench size 3/8		Replace ?? With PL = Plain or ZP = Zinc	

7/8 Unc - 9 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
7/8	U12 22022??	25	
1"	U12 22025??	25	
Wrench size 1/2		Replace ?? With PL = Plain or ZP = Zinc	

Continued next page




UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

Continued from previous page

7/8 Unc - 9 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
1-1/4"	U12 22032??	25	
1-1/2"	U12 22038??	25	
1-3/4"	U12 22045??	25	
2"	U12 22050??	25	
2-1/4"	U12 22057??	25	
2-1/2"	U12 22063??	25	
3"	U12 22075??	25	
3-1/2"	U12 22088??	25	
4"	U12 22100??	10	
4-1/2"	U12 22112??	10	
5"	U12 22125??	10	
5-1/2"	U12 22138??	10	
6"	U12 22150??	10	



Wrench size 1/2

Replace ?? With PL = Plain or ZP = Zinc

1" Unc - 8 tpi

Length	Code	Plain	Zinc
		Pack Quantity (if available)	
1"	U12 25025??	25	
1-1/4"	U12 25032??	25	
1-1/2"	U12 25038??	25	
1-3/4"	U12 25045??	25	
2"	U12 25050??	25	
2-1/4"	U12 25057??	25	
2-1/2"	U12 25063??	25	
2-3/4"	U12 25069??	10	
3"	U12 25075??	10	
3-1/2"	U12 25088??	10	
4"	U12 25100??	10	
4-1/2"	U12 25112??	10	
5"	U12 25125??	10	
5-1/2"	U12 25138??	10	
6"	U12 25150??	10	

Wrench size 9/16

Replace ?? With PL = Plain or ZP = Zinc



UNC Socket Set (Grub) Screw - Cup Point - Alloy Steel

1-1/8" Unc - 7 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1"	U12 28025??	1	
1-1/4"	U12 28032??	1	
1-1/2"	U12 28038??	1	
1-3/4"	U12 28045??	1	
2"	U12 28050??	1	
2-1/2"	U12 28063??	1	
3"	U12 28075??	1	



Wrench size 9/16

Replace ?? With PL = Plain or ZP = Zinc

1-1/4" Unc - 7 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1"	U12 32025??	1	
1-1/4"	U12 32032??	1	
1-1/2"	U12 32038??	1	
2"	U12 32050??	1	
2-1/2"	U12 32063??	1	
3"	U12 32075??	1	
3-1/2"	U12 32088??	1	
4"	U12 32100??	1	

Wrench size 5/8

Replace ?? With PL = Plain or ZP = Zinc

1-1/2" Unc - 6 tpi

Length	Code	Plain	Zinc
Pack Quantity (if available)			
1-1/2"	U12 38038??	1	
2"	U12 38050??	1	
2-1/2"	U12 38063??	1	
3"	U12 38075??	1	
3-1/2"	U12 38088??	1	
4"	U12 38100??	1	

Wrench size 3/4

Replace ?? With PL = Plain or ZP = Zinc