



Button Head Socket Screw - UNC - Alloy Steel

#10 Unc - 24 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U29 05006??	1/4	100	100
U29 05008??	5/16	100	100
U29 05010??	3/8	100	100
U29 05012??	1/2	100	100
U29 05016??	5/8	100	100
U29 05020??	3/4	100	100
U29 05022??	7/8	100	100
U29 05025??	1"	100	100
U29 05032??	1-1/4"	100	100
U29 05038??	1-1/2"	100	100
U29 05045??	1-3/4"	100	100
U29 05050??	2"	100	100
U29 05057??	2-1/4"	100	
U29 05063??	2-1/2"	100	100
Wrench size 1/8		Replace ?? With PL = Plain or ZP = Zinc	



1/4 Unc - 20 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U29 06006??	1/4	100	100
U29 06008??	5/16	100	
U29 06010??	3/8	100	100
U29 06012??	1/2	100	100
U29 06016??	5/8	100	100
U29 06020??	3/4	100	100
U29 06022??	7/8	100	100
U29 06025??	1"	100	100
U29 06032??	1-1/4"	100	100
U29 06038??	1-1/2"	100	100
U29 06045??	1-3/4"	100	100
U29 06050??	2"	100	100
U29 06063??	2-1/2"	100	100
U29 06075??	3"	100	
U29 06088??	3-1/2"	100	
U29 06100??	4"	100	
Wrench size 5/32		Replace ?? With PL = Plain or ZP = Zinc	



5/16 Unc - 18 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U29 08010??	3/8	100	100
U29 08012??	1/2	100	100
U29 08016??	5/8	100	100
U29 08020??	3/4	100	100
U29 08022??	7/8	100	100
U29 08025??	1"	100	100
U29 08032??	1-1/4"	100	100
U29 08038??	1-1/2"	100	100
U29 08045??	1-3/4"	100	100
U29 08050??	2"	100	100
U29 08057??	2-1/4"	100	
U29 08063??	2-1/2"	100	100
U29 08075??	3"	100	
U29 08088??	3-1/2"	100	
U29 08100??	4"	100	



Wrench size 3/16

Replace ?? With PL = Plain or ZP = Zinc

3/8 Unc - 16 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U29 10010??	3/8	100	
U29 10012??	1/2	100	100
U29 10016??	5/8	100	100
U29 10020??	3/4	100	100
U29 10022??	7/8	100	100
U29 10025??	1"	100	100
U29 10032??	1-1/4"	100	100
U29 10038??	1-1/2"	100	100
U29 10045??	1-3/4"	100	100
U29 10050??	2"	100	100
U29 10057??	2-1/4"	100	100
U29 10063??	2-1/2"	50	50
U29 10069??	2-3/4"	50	50
U29 10075??	3"	50	50
U29 10088??	3-1/2"	50	
U29 10100??	4"	50	

Wrench size 7/32

Replace ?? With PL = Plain or ZP = Zinc



1/2 Unc - 13 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U29 12020??	3/4	100	50
U29 12022??	7/8	100	
U29 12025??	1"	100	50
U29 12032??	1-1/4"	100	50
U29 12038??	1-1/2"	100	50
U29 12045??	1-3/4"	50	50
U29 12050??	2"	50	50
U29 12057??	2-1/4"	50	
U29 12063??	2-1/2"	50	50
U29 12075??	3"	50	50
U29 12020??	3-1/2"	25	
U29 12020??	4"	25	
Wrench size 5/16		Replace ?? With PL = Plain or ZP = Zinc	



5/8 Unc - 11 tpi

Code	Length	Plain	Zinc
Pack Quantity (if available)			
U29 16025??	1"	50	50
U29 16032??	1-1/4"	50	50
U29 16038??	1-1/2"	50	50
U29 16045??	1-3/4"	50	50
U29 16050??	2"	50	50
U29 16057??	2-1/4"	25	25
U29 16063??	2-1/2"	25	25
U29 16075??	3"	25	25
U29 16100??	4"	10	
Wrench size 3/8		Replace ?? With PL = Plain or ZP = Zinc	